



# SPEARHEAD

## LOCATING SERVICES

### UTILITY SURVEY REPORT

|                  |                                     |
|------------------|-------------------------------------|
| <b>DATE:</b>     | 11/16/23                            |
| <b>CUSTOMER:</b> | Ventura college                     |
| <b>PROJECT:</b>  | head house water science hoop house |
| <b>ADDRESS:</b>  |                                     |

|                                            |     |
|--------------------------------------------|-----|
| <b>Customer supply as built drawings:</b>  | No  |
| <b>Findings walkthrough with customer:</b> | Yes |
|                                            |     |

**Work Performed:** Located utilities in area for new hoop houses. Used Electromagnetic Locator and GPR

|                               |                                                 |
|-------------------------------|-------------------------------------------------|
| <b>Utilities located:</b>     | Electric, water, gas, irrigation and 2 unknown. |
| <b>Utilities NOT located:</b> | Sewer, comm.                                    |

**Job Summary:** Located, Painted, flagged and GPS mapped utilities.








White line is an abandoned electric line.





















Electric is approximately 2'6" deep, water is approximately 18" the 2 unknown lines could not get a depth.





















